

PMA Supplement Listing Alabama Supplement #25

Jet Parts Engineering, Inc.
25303 Profit Drive
Daphne, AL 36526

PMA NO. PQ1739CE
Supplement #25
Issued: Feb 23, 2007

<u>PMA Part Name</u>	<u>PMA Part Number</u>	<u>Approved Replacement for (OEM) Part Number</u>	<u>Make Eligibility</u>	<u>Model Eligibility</u>
Ring-Mating	297033JP	Vickers 297033	Bombardier	CL-600-2B19
Yoke	362546JP	Vickers 362546	Bombardier	CL-600-2B19
Element	405243JP	Vickers 405243	Bombardier	CL-600-2B19
Packing	624912JP	Vickers 624912	Bombardier	CL-600-2B19
Packing	3029021JP-001	Vickers 3029021-001	Bombardier	CL-600-2B19
Guide, Spring	518163JP	Vickers 518163	Bombardier	CL-600-2B19
Vane	2793956JP-101	Parker 2793956-101	Boeing	747-400, -400D & F series 757-200, -200C & PF series 767-200, -300, -300F
Rotor Assembly	848525JP	Eaton-Vickers 848525	Bombardier	CL-600-2B19
Plate	887299JP	Eaton-Vickers 887299	Bombardier	CL-600-2B19
Plate, Hold Down, Series (Standard)	887346JP	Eaton-Vickers 887346	Bombardier	CL-600-2B19

*This supplement listing is not endorsed by the FAA. For the original copy of the Jet Parts Engineering supplement, please contact sales@jetpartsengineering.com or call 206-281-0963.

PMA Supplement Listing Alabama Supplement #25

<u>PMA Part Name</u>	<u>PMA Part Number</u>	<u>Approved Replacement for (OEM) Part Number</u>	<u>Make Eligibility</u>	<u>Model Eligibility</u>
Plate, Hold Down (.001 Oversize)	887347JP	Eaton-Vickers 887347	Bombardier	CL-600-2B19
Plate, Hold Down (.002 Oversize)	887348JP	Eaton-Vickers 887348	Bombardier	CL-600-2B19
Plate, Hold Down (.003 Oversize)	887349JP	Eaton-Vickers 887349	Bombardier	CL-600-2B19
Plate, Hold Down (.005 Oversize)	887350JP	Eaton-Vickers 887350	Bombardier	CL-600-2B19
Plate, Hold Down (.007 Oversize)	887351JP	Eaton-Vickers 887351	Bombardier	CL-600-2B19
Plate, Hold Down (.0085 Oversize)	8873515JP	Eaton-Vickers 887351	Bombardier	CL-600-2B19
Ring, Piston	3163268JP-4	Honeywell 3163268-4	Bombardier	CL-600-2B19
Ring, Piston	3163268JP-11	Honeywell 3163268-11	Bombardier	CL-600-2B19
Poppet	3165433JP-1	Honeywell 3165433-1	Bombardier	CL-600-2B19
Poppet	3163811JP-3	Honeywell 3163811-3	Bombardier	CL-600-2B19
Poppet	3163811JP-7	Honeywell 3163811-7	Bombardier	CL-600-2B19

*This supplement listing is not endorsed by the FAA. For the original copy of the Jet Parts Engineering supplement, please contact sales@jetpartsengineering.com or call 206-281-0963.

PMA Supplement Listing Alabama Supplement #25

<u>PMA Part Name</u>	<u>PMA Part Number</u>	<u>Approved Replacement for (OEM) Part Number</u>	<u>Make Eligibility</u>	<u>Model Eligibility</u>
Guide Plate	3163812JP-2	Honeywell 3163812-2	Bombardier	CL-600-2B19
Guide Plate	3163812JP-10	Honeywell 3163812-10	Bombardier	CL-600-2B19
Guide Plate	3163812JP-12	Honeywell 3163812-12	Bombardier	CL-600-2B19
Switch Assembly	3170331JP-16	Honeywell 3170331-16	Boeing	757-200, -200PF, -300 series
Switch Assembly	3170331JP-20	Honeywell 3170331-20	Boeing	757-200, -200PF, -300 series
Tube	3170331JP-51	Honeywell 3170331-51	Boeing	757-200, -200PF, -300 series
Cover	3171798JP-1	Honeywell 3171798-1	Boeing	757-200, -200PF, -300 series
Switch	684-533-9008JP	Honeywell 62008-2 (684-533-9008)	Boeing	757-200, -200PF, -300 series

*This supplement listing is not endorsed by the FAA. For the original copy of the Jet Parts Engineering supplement, please contact sales@jetpartsengineering.com or call 206-281-0963.