

PMA Supplement Listing Alabama Supplement #33

Jet Parts Engineering, Inc.
25303 Profit Drive
Daphne, AL 36526

PMA NO. PQ1739CE
Supplement #33
Issued: August 31, 2007

<u>PMA Part Name</u>	<u>PMA Part Number</u>	<u>Approved Replacement for (OEM) Part Number</u>	<u>Make Eligibility</u>	<u>Model Eligibility</u>
Stator	3502771JP-1	Honeywell 3502771-1	Airbus	A319 A320 A321
Stator	3502771JP-3	Honeywell 3502771-3	Airbus	A319 A320 A321 A340
Deflector	3507560JP-4	Honeywell 3507560-4	Airbus	A319 A320 A321
Poppet	2862000JP-101	Parker 2862000-101	Boeing	737-300 737-400 737-500 737-600 737-700 737-800 737-900
Impeller	22264JP-1	Sundstrand 22264-1	Boeing	737-200 737-300 737-400 737-500
Cam	4110224JP-3	4110224-3	Boeing	767-200, -300, -400
Plate	4110228JP-2	4110229-2	Boeing	767-200, -300, -400

*This supplement listing is not endorsed by the FAA. For the original copy of the Jet Parts Engineering supplement, please contact sales@jetpartsengineering.com or call 206-281-0963.

PMA Supplement Listing Alabama Supplement #33

<u>PMA Part Name</u>	<u>PMA Part Number</u>	<u>Approved Replacement for (OEM) Part Number</u>	<u>Make Eligibility</u>	<u>Model Eligibility</u>
Lock Washer	4110370JP-1	4110370-1	Boeing	767-200, -300
Retainer	2686130JP	2686130	Boeing	767-200, -300
Seal	4110351JP-3	4110351-3	Boeing	767-200, -300
Bolt	4110371JP-1	4110371-1	Boeing	767-200, -300
Seal	4110418JP-2	4110418-2	Boeing	767-200, -300
Cover	228-50072-801JP	Bombardier 228-50072-801	Bombardier	CL-600-2B19
Plate	601R41450JP-9	Bombardier 601R41450-9	Bombardier	CL-6002C10 CL-600-2D24

*This supplement listing is not endorsed by the FAA. For the original copy of the Jet Parts Engineering supplement, please contact sales@jetpartsengineering.com or call 206-281-0963.